


Relay Board Assembly (0521B-000)

FOR USE WITH MODELS: CV-350, CV-350C,
CV-353, CV-353C

Warning: Disconnect electrical supply before servicing unit. Failure to do could result in serious injury or death. Disconnect old lead wires and reconnect per the wiring diagram below.

The relay assembly you are replacing may not have the same wire appearance as the new assembly. Please note the following changes:

1. The blue power lead wire has been changed to a black lead wire.
2. The red lead wire connected to the switch has been changed to a yellow lead wire.
3. For models manufactured after May 1997, two additional yellow lead wires are provided. If your power unit was manufactured prior to May 1997 and if these lead wires are not used either remove each lead from the terminal connection or cap each lead wire with an appropriate size wire nut.



Product specifications subject to change without notice.

NuTone®

4820 Red Bank Road, Cincinnati, Ohio 45227
Printed in U.S.A., Rev. 4/01, Part No. 0522B